

SECUR. CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATION PAGE

1a. REPORT SECURITY CLASSIFICATION <b>UNCLASSIFIED</b>		1b. RESTRICTIVE MARKINGS	
2a. SECURITY CLASSIFICATION AUTHORITY		3. DISTRIBUTION/AVAILABILITY OF REPORT <b>Approved for public release; distribution unlimited.</b>	
2b. DECLASSIFICATION/DOWNGRADING SCHEDULE			
4. PERFORMING ORGANIZATION REPORT NUMBER(S) <b>NRL Memorandum Report 5472</b>		5. MONITORING ORGANIZATION REPORT NUMBER(S)	
6a. NAME OF PERFORMING ORGANIZATION <b>Naval Research Laboratory</b>	6b. OFFICE SYMBOL <i>(if applicable)</i>	7a. NAME OF MONITORING ORGANIZATION	
6c. ADDRESS (City, State, and ZIP Code) <b>Washington, DC 20375-5000</b>		7b. ADDRESS (City, State, and ZIP Code)	
8a. NAME OF FUNDING/SPONSORING ORGANIZATION <b>Department of Interior</b>	8b. OFFICE SYMBOL <i>(if applicable)</i>	9. PROCUREMENT INSTRUMENT IDENTIFICATION NUMBER	
8c. ADDRESS (City, State, and ZIP Code) <b>Mineral Management Service Reston, VA 22091</b>		10. SOURCE OF FUNDING NUMBERS	
		PROGRAM ELEMENT NO. <b>DOI</b>	PROJECT NO. <b>328</b>
		TASK NO.	WORK UNIT ACCESSION NO. <b>DN380-566</b>
11. TITLE (Include Security Classification) <b>Offshore Oil Platform Underwater Inspection: A Study and Evaluation of a Scanning Beam Sonar</b>			
12. PERSONAL AUTHOR(S) <b>Carey, E.W. and Ozimina, C.D.</b>			
13a. TYPE OF REPORT <b>Final</b>	13b. TIME COVERED FROM <b>8/83</b> TO <b>9/84</b>	14. DATE OF REPORT (Year, Month, Day) <b>1984 November 9</b>	15. PAGE COUNT <b>26</b>
16. SUPPLEMENTARY NOTATION			
17. COSATI CODES		18. SUBJECT TERMS (Continue on reverse if necessary and identify by block number)	
FIELD	GROUP	SUB-GROUP	
		Scanning beam sonar	
		Offshore oil platform inspection	
19. ABSTRACT (Continue on reverse if necessary and identify by block number) <p>This report examines a method to perform unannounced inspections of producing offshore oil platforms for possible structural deficiencies. An off-the-shelf scanning beam sonar imaging system was selected and evaluated at a candidate platform. The test results indicated that the scanning beam equipment must be located close to the structure for usable images. This requirement would necessitate permission from the operator. Possible modifications to the equipment tested are recommended.</p>			
20. DISTRIBUTION/AVAILABILITY OF ABSTRACT <input checked="" type="checkbox"/> UNCLASSIFIED/UNLIMITED <input type="checkbox"/> SAME AS RPT <input type="checkbox"/> DTIC USERS		21. ABSTRACT SECURITY CLASSIFICATION <b>UNCLASSIFIED</b>	
22a. NAME OF RESPONSIBLE INDIVIDUAL <b>E. W. Carey</b>		22b. TELEPHONE (Include Area Code) <b>(202) 767-2112</b>	22c. OFFICE SYMBOL <b>Code 5820</b>

DD FORM 1473, 84 MAR

83 APR edition may be used until exhausted. All other editions are obsolete.

SECURITY CLASSIFICATION OF THIS PAGE